

N/A

CDCU877AGQLR

Part Number:	CDCU877AGQLR
Manufacturer/Brand:	N/A
Product description:	IC PLL CLOCK DRIVER 1.8V 52-BGA
Datasheets:	
RoHS Status:	Contains lead / RoHS non-compliant
Stock Condition:	6514 pcs stock
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS

[REQUEST FOR QUOTATION](#)

Image may be representation. See specifications for product details.

Specifications of CDCU877AGQLR

PART NUMBER	CDCU877AGQLR
MANUFACTURER	N/A
DESCRIPTION	IC PLL CLOCK DRIVER 1.8V 52-BGA
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
QUANTITY AVAILABLE	6514 pcs
DATA SHEET	
VOLTAGE - SUPPLY	1.7 V ~ 1.9 V
SUPPLIER DEVICE PACKAGE	56-BGA MICROSTAR JUNIOR (7.0x4.5)
SERIES	-
RATIO - INPUT:OUTPUT	1:10
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	56-VFBGA
PLL	Yes
OUTPUT	SSTL-18
OPERATING TEMPERATURE	-40°C ~ 85°C
NUMBER OF CIRCUITS	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	2 (1 Year)
MAIN PURPOSE	Memory, DDR2
LEAD FREE STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
INPUT	SSTL-18
FREQUENCY - MAX	400MHz
DIFFERENTIAL - INPUT:OUTPUT	Yes/Yes
BASE PART NUMBER	CDCU877

Related Tags

CDCU877AGQLR	CDCU877AGQLR Distributor	CDCU877AGQLR Supplier
CDCU877AGQLR Price	CDCU877AGQLR Pictures	CDCU877AGQLR Image
CDCU877AGQLR PDF Datasheet	CDCU877AGQLR Download Datasheet	CDCU877AGQLR Datasheet
CDCU877AGQLR Stock	Buy CDCU877AGQLR	Buy CDCU877AGQLR
CDCU877AGQLR	Supplier	Distributor

Related Products

	<p>CDCU877ARHAR Manufacturers: N/A Description: IC PLL CLOCK DRIVER 1.8V 40VQFN In stock: 20815 pcs</p> <p>RFQ</p>		<p>CDCS503TPWRQ1 Manufacturers: N/A Description: IC CLK BUFFER 1:1 108MHZ 8TSSOP In stock: 132674 pcs</p> <p>RFQ</p>
	<p>CDCU877ARHATG4 Manufacturers: N/A Description: IC PLL CLOCK DRIVER 1.8V 40VQFN In stock: 16396 pcs</p> <p>RFQ</p>		<p>CDCU2A877ZQLR Manufacturers: N/A Description: IC PLL CLOCK DRIVER 1.8V 52-BGA In stock: 19558 pcs</p> <p>RFQ</p>
	<p>CDCS503PW Manufacturers: N/A Description: IC CLK BUFFER 1:1 108MHZ 8TSSOP In stock: 116452 pcs</p> <p>RFQ</p>		<p>CDCU877ARHARG4 Manufacturers: N/A Description: IC PLL CLOCK DRIVER 1.8V 40VQFN In stock: 25486 pcs</p> <p>RFQ</p>
	<p>CDCU877AGQLT Manufacturers: N/A Description: IC PLL CLOCK DRIVER 1.8V 52-BGA In stock: 2999 pcs</p> <p>RFQ</p>		<p>CDCS504TPWRQ1 Manufacturers: N/A Description: CLOCK FREQUENCY MULTIPLIER In stock: 68058 pcs</p> <p>RFQ</p>
	<p>CDCU877ARHAT Manufacturers: N/A Description: IC PLL CLOCK DRIVER 1.8V 40VQFN In stock: 15604 pcs</p> <p>RFQ</p>		<p>CDCU877ARTBR Manufacturers: N/A Description: IC PLL CLOCK DRIVER 1.8V 40-QFN In stock: 5044 pcs</p> <p>RFQ</p>
	<p>CDCU2A877ZQLT Manufacturers: N/A Description: IC PLL CLOCK DRIVER 1.8V 52-BGA In stock: 15289 pcs</p> <p>RFQ</p>		<p>CDCS503PWR Manufacturers: N/A Description: IC CLK BUFFER 1:1 108MHZ 8TSSOP In stock: 68875 pcs</p> <p>RFQ</p>

