



TDK Corporation

HHM1932A2

Part Number:	HHM1932A2
Manufacturer/Brand:	TDK Corporation
Product description:	BALUN 862MHZ-894MHZ 50/100 0402
Datasheets:	HHM1932A2.pdf
RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	1054239 pcs stock
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS

[REQUEST FOR QUOTATION](#)

Image may be representation. See specifications for product details.

Specifications of HHM1932A2

PART NUMBER	HHM1932A2
MANUFACTURER	TDK Corporation
DESCRIPTION	BALUN 862MHZ-894MHZ 50/100 0402
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
QUANTITY AVAILABLE	1054239 pcs
DATA SHEET	HHM1932A2.pdf
SERIES	HHM
RETURN LOSS (MIN)	10dB
PHASE DIFFERENCE	180° ±10°
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	0402 (1005 Metric)
OTHER NAMES	445-175603-2
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INSERTION LOSS (MAX)	0.8dB
IMPEDANCE - UNBALANCED/BALANCED	50 / 100 Ohm
FREQUENCY RANGE	862MHz ~ 894MHz
DETAILED DESCRIPTION	RF Balun 862MHz ~ 894MHz 50 / 100 Ohm 0402 (1005 Metric)

Related Tags

TDK Corporation HHM1932A2	HHM1932A2 Distributor	HHM1932A2 Supplier
HHM1932A2 Price	HHM1932A2 Pictures	HHM1932A2 Image
HHM1932A2 PDF Datasheet	HHM1932A2 Download Datasheet	HHM1932A2 Datasheet
HHM1932A2 Stock	Buy HHM1932A2	Buy TDK Corporation HHM1932A2
TDK Corporation HHM1932A2	TDK Corporation Supplier	TDK Corporation Distributor
TDK Corporation HHM1932A2		

Related Products

<p>HHM1927A4 Manufacturers: TDK Corporation Description: BALUN 1.805-2.17GHZ 50/100 0402 In stock: 319228 pcs</p> <p>RFQ</p>	<p>HHM1906A1 Manufacturers: TDK Corporation Description: BALUN 4.9GHZ-5.95GHZ 50/75 0402 In stock: 3696 pcs</p> <p>RFQ</p>
<p>HHM1918A2 Manufacturers: TDK Corporation Description: BALUN 2.3GHZ-2.7GHZ 50/100 0402 In stock: 1190924 pcs</p> <p>RFQ</p>	<p>HHM1904C1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/75 0402 In stock: 47142 pcs</p> <p>RFQ</p>
<p>HHM22106C1 Manufacturers: TDK Corporation Description: RF DIR CPLR 700MHZ-2.7GHZ 0603 In stock: 1052355 pcs</p> <p>RFQ</p>	<p>HHM2202SA2 Manufacturers: TDK Corporation Description: RF DIR COUPLER 1.71-1.79GHZ 0603 In stock: 4048 pcs</p> <p>RFQ</p>
<p>HHM1917A5 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/50 0402 In stock: 335006 pcs</p> <p>RFQ</p>	<p>HHM22152A2 Manufacturers: TDK Corporation Description: RF DIR COUPLER 450-3800MHZ 1608 In stock: 1092054 pcs</p> <p>RFQ</p>
<p>HHM22137A2 Manufacturers: TDK Corporation Description: RF DIR COUPLER 698-2620MHZ 0603 In stock: 1214475 pcs</p> <p>RFQ</p>	<p>HHM1907B1 Manufacturers: TDK Corporation Description: BALUN 4.9GHZ-5.95GHZ 50/50 0402 In stock: 307944 pcs</p> <p>RFQ</p>
<p>HHM1946A1 Manufacturers: TDK Corporation Description: BALUN 2.3GHZ-2.7GHZ 50/100 0402 In stock: 62622 pcs</p> <p>RFQ</p>	<p>HHM2204SA1 Manufacturers: TDK Corporation Description: RF DIR COUPLR 1.71-1.785GHZ 0603 In stock: 237035 pcs</p> <p>RFQ</p>

