

N/A

CDCLVP111VF

Part Number:	CDCLVP111VF
Manufacturer/Brand:	N/A
Product description:	IC CLK BUFFER 2:10 3.5GHZ 32LQFP
Datasheets:	
RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	9064 pcs stock
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS

[REQUEST FOR QUOTATION](#)

Specifications of CDCLVP111VF

PART NUMBER	CDCLVP111VF
MANUFACTURER	N/A
DESCRIPTION	IC CLK BUFFER 2:10 3.5GHZ 32LQFP
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
QUANTITY AVAILABLE	9064 pcs
DATA SHEET	
VOLTAGE - SUPPLY	2.375 V ~ 3.8 V
TYPE	Fanout Buffer (Distribution), Multiplexer
SUPPLIER DEVICE PACKAGE	32-LQFP (7x7)
SERIES	-
RATIO - INPUT:OUTPUT	2:10
PACKAGING	Tray
PACKAGE / CASE	32-LQFP
OUTPUT	LVPECL
OTHER NAMES	296-24168 296-24168-5 296-24168-5-ND
OPERATING TEMPERATURE	-40°C ~ 85°C
NUMBER OF CIRCUITS	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INPUT	CML, LVDS, LVPECL, SSTL
FREQUENCY - MAX	3.5GHz
DIFFERENTIAL - INPUT:OUTPUT	Yes/Yes
DETAILED DESCRIPTION	Clock Fanout Buffer (Distribution), Multiplexer IC 2:10 3.5GHz 32-LQFP
BASE PART NUMBER	CDCLVP111

Related Tags

CDCLVP111VF	CDCLVP111VF Distributor	CDCLVP111VF Supplier
CDCLVP111VF Price	CDCLVP111VF Pictures	CDCLVP111VF Image
CDCLVP111VF PDF Datasheet	CDCLVP111VF Download Datasheet	CDCLVP111VF Datasheet
CDCLVP111VF Stock	Buy CDCLVP111VF	Buy CDCLVP111VF
CDCLVP111VF	Supplier	Distributor

Related Products

	<p>CDCLVP110VFRG4</p> <p>Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32LQFP In stock: 15445 pcs</p> <p>RFQ</p>		<p>CDCLVP1208RHDR</p> <p>Manufacturers: N/A Description: IC CLK BUFFER 2:8 2GHZ 28VQFN In stock: 9236 pcs</p> <p>RFQ</p>
	<p>CDCLVP110VFG4</p> <p>Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32LQFP In stock: 11455 pcs</p> <p>RFQ</p>		<p>CDCLVP1208EVM</p> <p>Manufacturers: N/A Description: EVAL MODULE FOR CDCLVP1208 In stock: 673 pcs</p> <p>RFQ</p>
	<p>CDCLVP1204RGTR</p> <p>Manufacturers: N/A Description: IC CLK BUFFER 2:4 2GHZ 16QFN In stock: 28155 pcs</p> <p>RFQ</p>		<p>CDCLVP111RHBR</p> <p>Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32QFN In stock: 7954 pcs</p> <p>RFQ</p>
	<p>CDCLVP110VFR</p> <p>Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32LQFP In stock: 14446 pcs</p> <p>RFQ</p>		<p>CDCLVP111VFR</p> <p>Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32LQFP In stock: 14177 pcs</p> <p>RFQ</p>
	<p>CDCLVP1204RGTT</p> <p>Manufacturers: N/A Description: IC CLK BUFFER 2:4 2GHZ 16QFN In stock: 12477 pcs</p> <p>RFQ</p>		<p>CDCLVP111RHBT</p> <p>Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32QFN In stock: 12166 pcs</p> <p>RFQ</p>
	<p>CDCLVP1204EVM</p> <p>Manufacturers: N/A Description: EVAL MODULE FOR CDCLVP1204 In stock: 587 pcs</p> <p>RFQ</p>		<p>CDCLVP111MVFREP</p> <p>Manufacturers: N/A Description: IC CLOCK BUFFER MUX 2:10 32LQFP In stock: 4577 pcs</p> <p>RFQ</p>