



TDK Corporation

HHM1776B2

Part Number:	HHM1776B2
Manufacturer/Brand:	TDK Corporation
Product description:	BALUN 824MHZ-894MHZ 50/50 0603
Datasheets:	HHM1776B2.pdf
RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	57084 pcs stock
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS

[REQUEST FOR QUOTATION](#)

Image may be representation. See specifications for product details.

Specifications of HHM1776B2

PART NUMBER	HHM1776B2
MANUFACTURER	TDK Corporation
DESCRIPTION	BALUN 824MHZ-894MHZ 50/50 0603
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
QUANTITY AVAILABLE	57084 pcs
DATA SHEET	HHM1776B2.pdf
SERIES	HHM
RETURN LOSS (MIN)	10dB
PHASE DIFFERENCE	180° ±10°
PACKAGING	Cut Tape (CT)
PACKAGE / CASE	0603 (1608 Metric)
OTHER NAMES	445-6864-1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INSERTION LOSS (MAX)	1.2dB
IMPEDANCE - UNBALANCED/BALANCED	50 / 50 Ohm
FREQUENCY RANGE	824MHz ~ 894MHz
DETAILED DESCRIPTION	RF Balun 824MHz ~ 894MHz 50 / 50 Ohm 0603 (1608 Metric)

Related Tags

TDK Corporation HHM1776B2	HHM1776B2 Distributor	HHM1776B2 Supplier
HHM1776B2 Price	HHM1776B2 Pictures	HHM1776B2 Image
HHM1776B2 PDF Datasheet	HHM1776B2 Download Datasheet	HHM1776B2 Datasheet
HHM1776B2 Stock	Buy HHM1776B2	Buy TDK Corporation HHM1776B2
TDK Corporation HHM1776B2	TDK Corporation Supplier	TDK Corporation Distributor
TDK Corporation HHM1776B2		

Related Products

<p>HHM1902A1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/50 0402 In stock: 189528 pcs RFQ</p>	<p>HHM1763B2 Manufacturers: TDK Corporation Description: BALUN 880MHZ-960MHZ 50/150 0603 In stock: 72443 pcs RFQ</p>
<p>HHM1775D1 Manufacturers: TDK Corporation Description: BALUN 3.1GHZ-4.9GHZ 50/100 0805 In stock: 261546 pcs RFQ</p>	<p>HHM1749S1 Manufacturers: TDK Corporation Description: BALUN 1.71-1.99GHZ 50/100 0603 In stock: 800377 pcs RFQ</p>
<p>HHM1902B1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/50 0402 In stock: 290984 pcs RFQ</p>	<p>HHM1733B1 Manufacturers: TDK Corporation Description: BALUN 4.9GHZ-5.95GHZ 50/50 0603 In stock: 144005 pcs RFQ</p>
<p>HHM1752A2 Manufacturers: TDK Corporation Description: BALUN 4.9GHZ-5.95GHZ 50/200 0603 In stock: 115644 pcs RFQ</p>	<p>HHM1903A1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/100 0402 In stock: 212246 pcs RFQ</p>
<p>HHM1779B1 Manufacturers: TDK Corporation Description: BALUN 2.11-2.17GHZ 50/100 0603 In stock: 261529 pcs RFQ</p>	<p>HHM1791A1 Manufacturers: TDK Corporation Description: BALUN 2.5GHZ-2.7GHZ 50/100 0603 In stock: 455498 pcs RFQ</p>
<p>HHM1776B3 Manufacturers: TDK Corporation Description: BALUN 880MHZ-960MHZ 50/50 0603 In stock: 188262 pcs RFQ</p>	<p>HHM1732B1 Manufacturers: TDK Corporation Description: BALUN 4.9GHZ-5.95GHZ 50/100 0603 In stock: 273182 pcs RFQ</p>

