

N/A

### CDCLVP110VFR

Part Number:	CDCLVP110VFR
Manufacturer/Brand:	N/A
Product description:	IC CLK BUFFER 2:10 3.5GHZ 32LQFP
Datasheets:	
RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	14446 pcs stock
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS

[REQUEST FOR QUOTATION](#)

#### Specifications of CDCLVP110VFR

PART NUMBER	CDCLVP110VFR
MANUFACTURER	N/A
DESCRIPTION	IC CLK BUFFER 2:10 3.5GHZ 32LQFP
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
QUANTITY AVAILABLE	14446 pcs
DATA SHEET	
VOLTAGE - SUPPLY	2.375 V ~ 3.8 V
TYPE	Fanout Buffer (Distribution), Multiplexer
SUPPLIER DEVICE PACKAGE	32-LQFP (7x7)
SERIES	-
RATIO - INPUT:OUTPUT	2:10
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	32-LQFP
OUTPUT	LVPECL
OPERATING TEMPERATURE	-40°C ~ 85°C
NUMBER OF CIRCUITS	1
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INPUT	HSTL, LVPECL
FREQUENCY - MAX	3.5GHz
DIFFERENTIAL - INPUT:OUTPUT	Yes/Yes
DETAILED DESCRIPTION	Clock Fanout Buffer (Distribution), Multiplexer IC 2:10 3.5GHz 32-LQFP
BASE PART NUMBER	CDCLVP110

#### Related Tags

<a href="#">CDCLVP110VFR</a>	<a href="#">CDCLVP110VFR Distributor</a>	<a href="#">CDCLVP110VFR Supplier</a>
<a href="#">CDCLVP110VFR Price</a>	<a href="#">CDCLVP110VFR Pictures</a>	<a href="#">CDCLVP110VFR Image</a>
<a href="#">CDCLVP110VFR PDF Datasheet</a>	<a href="#">CDCLVP110VFR Download Datasheet</a>	<a href="#">CDCLVP110VFR Datasheet</a>
<a href="#">CDCLVP110VFR Stock</a>	<a href="#">Buy CDCLVP110VFR</a>	<a href="#">Buy CDCLVP110VFR</a>
<a href="#">CDCLVP110VFR</a>	<a href="#">Supplier</a>	<a href="#">Distributor</a>

#### Related Products

	<p><b>CDCLVP110VFRG4</b></p> <p>Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32LQFP In stock: 15445 pcs</p> <p><a href="#">RFQ</a></p>		<p><b>CDCLVP110MVFRG4</b></p> <p>Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32LQFP In stock: 11462 pcs</p> <p><a href="#">RFQ</a></p>
	<p><b>CDCLVP110MVFR</b></p> <p>Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32LQFP In stock: 14837 pcs</p> <p><a href="#">RFQ</a></p>		<p><b>CDCLVP1102RGTR</b></p> <p>Manufacturers: N/A Description: IC CLK BUFFER 1:2 2GHZ 16QFN In stock: 31588 pcs</p> <p><a href="#">RFQ</a></p>
	<p><b>CDCLVP111MVFREP</b></p> <p>Manufacturers: N/A Description: IC CLOCK BUFFER MUX 2:10 32LQFP In stock: 4577 pcs</p> <p><a href="#">RFQ</a></p>		<p><b>CDCLVP111VFR</b></p> <p>Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32LQFP In stock: 14177 pcs</p> <p><a href="#">RFQ</a></p>
	<p><b>CDCLVP111RHBT</b></p> <p>Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32QFN In stock: 12166 pcs</p> <p><a href="#">RFQ</a></p>		<p><b>CDCLVP110VF</b></p> <p>Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32LQFP In stock: 7934 pcs</p> <p><a href="#">RFQ</a></p>
	<p><b>CDCLVP111RHBR</b></p> <p>Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32QFN In stock: 7954 pcs</p> <p><a href="#">RFQ</a></p>		<p><b>CDCLVP111VF</b></p> <p>Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32LQFP In stock: 9064 pcs</p> <p><a href="#">RFQ</a></p>
	<p><b>CDCLVP110VFG4</b></p> <p>Manufacturers: N/A Description: IC CLK BUFFER 2:10 3.5GHZ 32LQFP In stock: 11455 pcs</p> <p><a href="#">RFQ</a></p>		<p><b>CDCLVP1102RGTT</b></p> <p>Manufacturers: N/A Description: IC CLK BUFFER 1:2 2GHZ 16QFN In stock: 24348 pcs</p> <p><a href="#">RFQ</a></p>