



TDK Corporation

HHM1907B1

Part Number:	HHM1907B1
Manufacturer/Brand:	TDK Corporation
Product description:	BALUN 4.9GHZ-5.95GHZ 50/50 0402
Datasheets:	HHM1907B1.pdf
RoHs Status:	Lead free / RoHS Compliant
Stock Condition:	307944 pcs stock
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS

[REQUEST FOR QUOTATION](#)

Image may be representation. See specifications for product details.

Specifications of HHM1907B1

PART NUMBER	HHM1907B1
MANUFACTURER	TDK Corporation
DESCRIPTION	BALUN 4.9GHZ-5.95GHZ 50/50 0402
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
QUANTITY AVAILABLE	307944 pcs
DATA SHEET	HHM1907B1.pdf
SERIES	-
RETURN LOSS (MIN)	10dB
PHASE DIFFERENCE	180° ±10°
PACKAGING	Original-Reel®
PACKAGE / CASE	0402 (1005 Metric)
OTHER NAMES	445-15673-6
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INSERTION LOSS (MAX)	0.8dB
IMPEDANCE - UNBALANCED/BALANCED	50 / 50 Ohm
FREQUENCY RANGE	4.9GHz ~ 5.95GHz
DETAILED DESCRIPTION	RF Balun 4.9GHz ~ 5.95GHz 50 / 50 Ohm 0402 (1005 Metric)

Related Tags

TDK Corporation HHM1907B1	HHM1907B1 Distributor	HHM1907B1 Supplier
HHM1907B1 Price	HHM1907B1 Pictures	HHM1907B1 Image
HHM1907B1 PDF Datasheet	HHM1907B1 Download Datasheet	HHM1907B1 Datasheet
HHM1907B1 Stock	Buy HHM1907B1	Buy TDK Corporation HHM1907B1
TDK Corporation HHM1907B1	TDK Corporation Supplier	TDK Corporation Distributor
TDK Corporation HHM1907B1		

Related Products

<p>HHM2202SA2 Manufacturers: TDK Corporation Description: RF DIR COUPLER 1.71-1.79GHZ 0603 In stock: 4048 pcs RFQ</p>	<p>HHM1902B1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/50 0402 In stock: 290984 pcs RFQ</p>
<p>HHM1904C1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/75 0402 In stock: 47142 pcs RFQ</p>	<p>HHM1932A2 Manufacturers: TDK Corporation Description: BALUN 862MHZ-894MHZ 50/100 0402 In stock: 1054239 pcs RFQ</p>
<p>HHM1918A2 Manufacturers: TDK Corporation Description: BALUN 2.3GHZ-2.7GHZ 50/100 0402 In stock: 1190924 pcs RFQ</p>	<p>HHM1927A4 Manufacturers: TDK Corporation Description: BALUN 1.805-2.17GHZ 50/100 0402 In stock: 319228 pcs RFQ</p>
<p>HHM1917A5 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/50 0402 In stock: 335006 pcs RFQ</p>	<p>HHM1946A1 Manufacturers: TDK Corporation Description: BALUN 2.3GHZ-2.7GHZ 50/100 0402 In stock: 62622 pcs RFQ</p>
<p>HHM1903A4 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/100 0402 In stock: 314972 pcs RFQ</p>	<p>HHM1906A1 Manufacturers: TDK Corporation Description: BALUN 4.9GHZ-5.95GHZ 50/75 0402 In stock: 3696 pcs RFQ</p>
<p>HHM1903A1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/100 0402 In stock: 212246 pcs RFQ</p>	<p>HHM1904A1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/75 0402 In stock: 58057 pcs RFQ</p>

