



TDK Corporation

HHM17153A2

Part Number:	HHM17153A2
Manufacturer/Brand:	TDK Corporation
Product description:	BALUN 698MHZ-894MHZ 50/50 0603
Datasheets:	HHM17153A2.pdf
RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	387125 pcs stock
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS/EMS

[REQUEST FOR QUOTATION](#)

Image may be representation. See specifications for product details.

Specifications of HHM17153A2

PART NUMBER	HHM17153A2
MANUFACTURER	TDK Corporation
DESCRIPTION	BALUN 698MHZ-894MHZ 50/50 0603
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
QUANTITY AVAILABLE	387125 pcs
DATA SHEET	HHM17153A2.pdf
SERIES	-
RETURN LOSS (MIN)	10dB
PHASE DIFFERENCE	180° ±15°
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	0603 (1608 Metric), 6 PC Pad
OTHER NAMES	445-174295-2
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INSERTION LOSS (MAX)	1.5dB
IMPEDANCE - UNBALANCED/BALANCED	50 / 50 Ohm
FREQUENCY RANGE	698MHz ~ 894MHz
DETAILED DESCRIPTION	RF Balun 698MHz ~ 894MHz 50 / 50 Ohm 0603 (1608 Metric), 6 PC Pad

Related Tags

TDK Corporation HHM17153A2	HHM17153A2 Distributor	HHM17153A2 Supplier
HHM17153A2 Price	HHM17153A2 Pictures	HHM17153A2 Image
HHM17153A2 PDF Datasheet	HHM17153A2 Download Datasheet	HHM17153A2 Datasheet
HHM17153A2 Stock	Buy HHM17153A2	Buy TDK Corporation HHM17153A2
TDK Corporation HHM17153A2	TDK Corporation Supplier	TDK Corporation Distributor
TDK Corporation HHM17153A2		

Related Products

<p>HHM17146A1 Manufacturers: TDK Corporation Description: BALUN 1.92GHZ-2.17GHZ 50/50 0603 In stock: 920864 pcs RFQ</p>	<p>HHM17168B1 Manufacturers: TDK Corporation Description: BALUN 3.4GHZ-3.8GHZ 50/50 0603 In stock: 227544 pcs RFQ</p>
<p>HHM17125D1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/50 0603 In stock: 496156 pcs RFQ</p>	<p>HHM17139B1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/50 0603 In stock: 255709 pcs RFQ</p>
<p>HHM1715E1 Manufacturers: TDK Corporation Description: BALUN 3.3GHZ-3.9GHZ 50/100 0603 In stock: 54435 pcs RFQ</p>	<p>HHM17152A1 Manufacturers: TDK Corporation Description: BALUN 698MHZ-894MHZ 50/100 0603 In stock: 506941 pcs RFQ</p>
<p>HHM1726P1 Manufacturers: TDK Corporation Description: BALUN 880MHZ-960MHZ 50/100 0603 In stock: 981103 pcs RFQ</p>	<p>HHM17139B2 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.6GHZ 50/50 0603 In stock: 823244 pcs RFQ</p>
<p>HHM1726N1 Manufacturers: TDK Corporation Description: BALUN 824MHZ-915MHZ 50/100 0603 In stock: 769871 pcs RFQ</p>	<p>HHM17165A1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.8GHZ 50/50 0603 In stock: 273962 pcs RFQ</p>
<p>HHM17166A1 Manufacturers: TDK Corporation Description: BALUN 1.9GHZ-2.3GHZ 50/50 0603 In stock: 247743 pcs RFQ</p>	<p>HHM17144A1 Manufacturers: TDK Corporation Description: BALUN 791MHZ-960MHZ 50/100 0603 In stock: 862583 pcs RFQ</p>

